REQUEST FOR INSPECTION

1.12/22		
CALL DATE: 10/3/23	TIME:_	
PROPERTY ADDRESS: 345 Piney Point Rd PERMIT NUMBER: # 19852		
INSPECTOR		
□ Bob Baldwin □ Jason Bienek □ Cary Moran □ Jose Gomez □ City Engineer □ Co/c / K		
Demolition	Generator Concrete Steel Pad	Mechanical Cover
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal
Piers	Fence Final	Mechanical Box Seal
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)
Ridge Height - Verification	Synthetic Turf	Mechanical Final (Wine Room)
Stair Compliance	Electrical T-Pole	Sewer Disconnect
Framing Only	Electrical Cover	Plumbing Water Line
Frame Cover	Electrical Ditch Cover	Plumbing Sewer Line
Poly Seal	Electrical TCI	Plumbing Ground
Insulation	Electrical Reconnect	Plumbing Shower Pan/Wall Board
Wall Board Interior	Pool Electrical Underground	Plumb Gas: House / Pool / Generator
Brick Tie	Pool Electrical Cover	Plumbing Cover
Stucco Lathe	Pool Electrical Final	Plumbing Final
Building Final	Electrical Final	Pool Plumbing Cover
Tree Final	Temporary Drainage	Pool Plumbing Vacuum Breaker, P-Trap
Driveway / Steel	Drainage Partial	Plumbing Pool Final
Driveway Final	Drainage Cover	Water Heater Final
Sidewalk/Flatwork/Pavers Steel	Drainage Final	Irrigation Trench / Final
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Cover / Final	Other/Miscellaneous
CONTRACTOR NAME: Jaced Fuller PASS FAIL		
	DATE: 10/3/23	
INSPECTOR COMMENTS: Tellepseo Tollepseo Time: 11:00		
INSPECTOR: (A)		
Phase 2 Fencing being Installed. Re-Inspection Fee Required		
Phase I Fencing being Installed. Like-inspection ree Required		
Grading on West Lot OK. Ensure fine grading		
I stoped into St. Francis from Fenceline		
A Seolist Latte St. Leavest Landier Children C.		
Need to re-inspect aroling behalfact?		
Lots. Appears anading to modified intets		
incomplete las cont near tree		
incomplete. Low spot near tree and power pole.		