REQUEST FOR INSPECTION

REQUEST FOR INSPECTION		
CALL DATE: 12/13/22 TIME : TIME		
PROPERTY ADDRESS: 11505 Memorial PERMIT NUMBER: 19351		
INSPECTOR ☐ Bob Baldwin ☐ Jason Bienek ☐ Cary Moran ☐ Jose Gomez ☐ City Engineer ☐ Community		
Demolition	Generator Concrete Steel Pad	Mechanical Cover
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal
Piers	Fence Final	Mechanical Box Seal
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)
Ridge Height - Verification	Synthetic Turf	Mechanical Final (Wine Room)
Stair Compliance	Electrical T-Pole	Sewer Disconnect
Framing Only	Electrical Cover	Plumbing Water Line
Frame Cover	Electrical Ditch Cover	Plumbing Sewer Line
Poly Seal	Electrical TCI	Plumbing Ground
Insulation	Electrical Reconnect	Plumbing Shower Pan/Wall Board
Wall Board Interior	Pool Electrical Underground	Plumb Gas: House / Pool / Generator
Brick Tie	Pool Electrical Cover	Plumbing Cover
Stucco Lathe	Pool Electrical Final	Plumbing Final
Building Final	Electrical Final	Pool Plumbing Cover
Tree Final	(Temporary Drainage	Pool Plumbing Vacuum Breaker, P-Trap
Driveway / Steel	Drainage Partial	Plumbing Pool Final
Driveway Final	Drainage Cover	Water Heater Final
Sidewalk/Flatwork/Pavers Steel	Drainage Final	Irrigation Trench / Final
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Cover / Final	Other/Miscellaneous
CONTRACTOR NAME: Build	48	PASS FAIL
CONTACT PHONE/EMAIL: # 832 428 - 0649		DATE: /2/15/22
INSPECTOR COMMENTS: TIME: /=45 AF.14.		
Tie in to city inlet must INSPECTOR: Color dece		
be complete as shown on Re-Inspection Fee Required		
drainage plan.		
RFFF needed around front property.		
Appears line o	on the East side	a lot was
Constructed into	miorcect inlet, not	- shown on drainag
plan Inlet fied	into is further	Bust. recommend
Tevise drainage plan, to show fie in on		
more Eastern intet; us well as cersize pine		
in-between to allow for drainage.		
BK to cover all other proper		