## REQUEST FOR INSPECTION

CALL DATE: 4/28/2022 TIME :AM / PM		
PROPERTY ADDRESS: PERMIT NUMBER: PERMIT NUMBER:		
INSPECTOR  ☐ Bob Baldwin ☐ Jason Bienek ☐ Cary Moran ☐ Jose Gomez ☐ City Engineer		
Demolition	Generator Concrete Steel Pad	Mechanical Cover
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal
Piers	Fence Final	Mechanical Box Seal
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)
Ridge Height - Verification	Synthetic Turf	Mechanical Final (Wine Room)
Stair Compliance	Electrical T-Pole	Sewer Disconnect
Framing Only	Electrical Cover	Plumbing Water Line
Frame Cover	Electrical Ditch Cover	Plumbing Sewer Line
Poly Seal	Electrical TCI	Plumbing Ground
Insulation	Electrical Reconnect	Plumbing Shower Pan/Wall Board
Wall Board Interior	Pool Electrical Underground	Plumb Gas: House / Pool / Generator
Brick Tie	Pool Electrical Cover	Plumbing Cover
Stucco Lathe	Pool Electrical Final	Plumbing Final
Building Final	Electrical Final	Pool Plumbing Cover
Tree Final	Temporary Drainage	Pool Plumbing Vacuum Breaker, P-Trap
Driveway / Steel	Drainage Partial	Plumbing Pool Final
Driveway Final	Drainage Cover	Water Heater Final
Sidewalk/Flatwork/Pavers Steel	Drainage Final	Irrigation Trench / Final
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Cover / Final	Other/Miscellaneous
CONTRACTOR NAME: Martin Sure Sure Sure Sure Sure Sure Sure Sure		PASS FAIL
CONTACT PHONE/EMAIL:	361-4507p)	DATE: 4/28/22
INSPECTOR COMMENTS:		
- Per last inspection in August 2021, INSPECTOR: Aann Cioling		
Several extra inlets and pipe on Re-Inspection Fee Required		
properly that are not shown on drainage plan.		
- Type A inlets shown on existing pipe in ROW on drainge		
plan, but boxes do not have grate inlet tops to		
copture storm water		
- Surp pump not shown in drivage plan		
- Existing Rep ppe in SE corner of payinty not shown on plan		
- Need to revive drainage plan to retlect field changes - Appears to be low spot on NW corner of lot		
- Appears to be low spot on NW corner of lot		