

REQUEST FOR INSPECTION

CALL DATE: 4/6/23 TIME _____: _____ AM / PM

PROPERTY ADDRESS: 226 Millbrook St PERMIT NUMBER: #19626

INSPECTOR

Bob Baldwin Jason Bienek Cary Moran Jose Gomez City Engineer

Cole w HDR
Eng'g

Demolition	Generator Concrete Steel Pad	Mechanical Cover
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal
Piers	Fence Final	Mechanical Box Seal
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)
Ridge Height - Verification	Synthetic Turf	Mechanical Final (Wine Room)
Stair Compliance	Electrical T-Pole	Sewer Disconnect
Framing Only	Electrical Cover	Plumbing Water Line
Frame Cover	Electrical Ditch Cover	Plumbing Sewer Line
Poly Seal	Electrical TCI	Plumbing Ground
Insulation	Electrical Reconnect	Plumbing Shower Pan/Wall Board
Wall Board Interior	Pool Electrical Underground	Plumb Gas: House / Pool / Generator
Brick Tie	Pool Electrical Cover	Plumbing Cover
Stucco Lathe	Pool Electrical Final	Plumbing Final
Building Final	Electrical Final	Pool Plumbing Cover
Tree Final	Temporary Drainage	Pool Plumbing Vacuum Breaker, P-Trap
Driveway / Steel	Drainage Partial	Plumbing Pool Final
Driveway Final	<u>Drainage Cover</u>	Water Heater Final
Sidewalk/Flatwork/Pavers Steel	Drainage Final	Irrigation Trench / Final
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Cover / Final	Other/Miscellaneous

CONTRACTOR NAME: Steven Davidoff

CONTACT PHONE/EMAIL: #713.539.0030

INSPECTOR COMMENTS: Rainbow Construction

<u>Pass</u> PASS FAIL
DATE: <u>4-6-23</u>
TIME: <u>11:00</u>
INSPECTOR: <u>Cole</u>

Re-Inspection Fee Required

Okay to cover length of pipes.

Need to re-inspect each pipe connection to inlet. Must see generous amount of tar seal to ensure water tight on inside and outside of connection.

recommend filling inlet bottoms with grout.