

Plumbing

REQUEST FOR ELECTRICAL INSPECTION

DATE: 2-24-21 TIME _____: AM / PM

JOB ADDRESS: 621 Piney Point

PERMIT NUMBER: 17579

INSPECTION DATE: 2-25-21

Codes Used: **NFPA 70 - NEC 2017**

ELECTRICAL INSPECTORS: 1) Jason Bienek 2) Bob Baldwin

- 1. Temp Sump Pump Connection
- 2. T-pole
- 3. Ditch Cover
- 4. Slab Cover
- 5. Wall / Ceiling Cover
- 6. TCI
- 7. Meter Loop And Service
- 8. Reconnect
- 9. Electrical Final
- 10. Landscape Lighting Cover
- 11. Landscape Lighting Final

Plumbing
Rough in

- 1. Electrical Pool Cover
- 2. Electrical Pool Final
- 1. Generator Ditch Cover
- 2. Generator Electrical Final
- 1. Partial / See Comments

PASS	FAIL
DATE: <u>2-25-21</u>	
TIME: <u>11:05</u>	
INSPECTOR: <u>Bob Baldwin 3330</u>	

CONTRACTOR/CALLER NAME: Mammoth Plumbing

CONTACT TEL/PGR/MOBILE: 281-398-1700

INSPECTOR COMMENTS: _____

Reinspection fee required

Plumbing
REQUEST FOR ELECTRICAL INSPECTION

DATE: 2-22-21 TIME: _____ : AM / PM

JOB ADDRESS: 621 Piney Point

PERMIT NUMBER: 17579

INSPECTION DATE: 2-22-21

Codes Used: **NFPA 70 - NEC 2017**

ELECTRICAL INSPECTORS: 1) Jason Bienek 2) Bob Baldwin

- 1. Temp Sump Pump Connection
- 2. T-pole
- 3. Ditch Cover
- 4. Slab Cover
- 5. Wall / Ceiling Cover
- 6. TCI
- 7. Meter Loop And Service
- 8. Reconnect
- 9. Electrical Final
- 10. Landscape Lighting Cover
- 11. Landscape Lighting Final

*Plumbing
Cover*

- 1. Electrical Pool Cover
- 2. Electrical Pool Final
- 1. Generator Ditch Cover
- 2. Generator Electrical Final
- 1. Partial / See Comments

PASS	<u>FAIL</u>
DATE:	<u>2-22-21</u>
TIME:	<u>10:15</u>
INSPECTOR:	<u>BhB 3332</u>

CONTRACTOR/CALLER NAME: Mammoth Plumbing
CONTACT TEL/PGR/MOBILE: 281-398-1700 Melanie Berk

INSPECTOR COMMENTS: _____

No pressure on gas gauge
2 water lines to kitchen island not connected.
North side attic, walk in, ~~and~~ vent pipes blocking AC equipment from being serviced or being changed out. Must have 30" of clearance in front of AC equipment.
A Water heater in same area not vented. All ductwork cannot be touching water heater, pipes or flue pipe.
Vacuum breakers on hose bibs.

Reinspection fee required