

# REQUEST FOR INSPECTION

CALL DATE: 2/1/2024 TIME 9 : 21 AM / PM

PROPERTY ADDRESS: 11315 Smithdale Rd PERMIT NUMBER: 20367

### INSPECTOR

Bob Baldwin 
  Jason Bienek 
  Cary Moran 
  Jose Gomez 
  City Engineer Grant Moyer (HDR)

Demolition	Generator Concrete Steel Pad	Mechanical Cover
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal
Piers	Fence Final	Mechanical Box Seal
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)
Ridge Height - Verification	Synthetic Turf	Mechanical Final (Wine Room)
Stair Compliance	Electrical T-Pole	Sewer Disconnect
Framing Only	Electrical Cover	Plumbing Water Line
Frame Cover	Electrical Ditch Cover	Plumbing Sewer Line
Poly Seal	Electrical TCI	Plumbing Ground
Insulation	Electrical Reconnect	Plumbing Shower Pan/Wall Board
Wall Board Interior	Pool Electrical Underground	Plumb Gas: House / Pool / Generator
Brick Tie	Pool Electrical Cover	Plumbing Cover
Stucco Lathe	Pool Electrical Final	Plumbing Final
Building Final	Electrical Final	Pool Plumbing Cover
Tree Final	<u>Temporary Drainage</u>	Pool Plumbing Vacuum Breaker, P-Trap
Driveway / Steel	<u>Drainage Partial</u>	Plumbing Pool Final
Driveway Final	Drainage Cover	Water Heater Final
Sidewalk/Flatwork/Pavers Steel	Drainage Final	Irrigation Trench / Final
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Cover / Final	Other/Miscellaneous

CONTRACTOR NAME: Shane Wipac

CONTACT PHONE/EMAIL: 832 977 7167

INSPECTOR COMMENTS: \_\_\_\_\_

PASS <span style="margin-left: 50px;"><u>FAIL</u></span>
DATE: <u>2/1/24</u>
TIME: <u>9:21</u>
INSPECTOR: <u>Grant Moyer</u>

Re-Inspection Fee Required

OK to cover inlet 13 through  
7 OK to cover inlet 1 through  
6 Line 7 is NOT OK to cover due to  
standing water  
west  
Remaining pipes on NW side were unable  
to be seen. Need to be uncovered.  
Tie-in not done w/ city inlet