

REQUEST FOR PLUMBING / MECHANICAL INSPECTION

DATE: 09.10.2014 TIME: _____ : _____ AM / PM
 JOB ADDRESS: 11519 Dunsinane Street
 PERMIT NUMBER: (Mike Peloguin) # 12188

- Pass Fail Street Clean In Front of Property- (Nothing in Gutter)
- Pass Fail Dirt, Mud, Construction Tracks in Front of Property
- Pass Fail Trash Anywhere on Property
- Pass Fail O-Tolerance for Lunch Trash This May Result in Project to be Temporarily Shut Down!
- Pass Fail Dumpster full to the Lip & Needs to be Serviced
- Pass Fail Port-O-Can Door Facing Away From Street
- Pass Fail Port-O-Can Screened and/or Needs Maintenance
- Pass Fail Tree Protective Fencing Down
- Pass Fail Filter Fabric Fencing Down
- Pass Fail High Grass and/or Tall Weeds
- Pass Fail Overall Condition of Construction Site Good _____ Poor
- _____ Verbal Warning _____ Site Cleaned at Insp. _____ City Citation Issued _____ City Notified

Thursday

INSPECTOR : Joe Moore w/ HD12 Cendine INSPECTION DATE: 09.11.14

PLUMBING	MECHANICAL
1. Water line <input type="checkbox"/>	1. Vent Hood <input type="checkbox"/>
2. Rough In <input type="checkbox"/>	2. Rough/cover <input type="checkbox"/>
3. Top Out <input type="checkbox"/>	3. Mech Final <input type="checkbox"/>
4. Shower Pan <input type="checkbox"/>	4. Water Heater Final <input type="checkbox"/>
5. Sewer Line <input type="checkbox"/>	5. Fire Sprinkler cover <input type="checkbox"/> <small>(need MVFD approval)</small>
6. WC Flange <input type="checkbox"/>	6. Fire Sprinkler Final <input type="checkbox"/>
7. GTO <input type="checkbox"/>	
8. Plumbing Final <input type="checkbox"/>	
9. Pool Drainage <input type="checkbox"/>	
10. <u>Site Drainage</u> <input checked="" type="checkbox"/>	
11. Irrigation Final <input type="checkbox"/>	
12. Other <input type="checkbox"/>	

(281) 367-4390(+)

PASS	FAIL
DATE: <u>9-11-14</u>	
TIME: <u>11:15</u>	
INSPECTOR: <u>Joe Moore</u>	

CONTRACTOR/CALLER NAME: Steve Horn (832) 928-4583
 CONTACT TEL/PGR/MOBILE: Horn Building Co.
 INSPECTOR COMMENTS: Site drainage inspection.
Site drainage final

2 inlets on back (south east area)
appear to be missing grot around
pipes tied it. 1 missing grate

Need to fix all down reinforce (Hew
fabric fence.

REQUEST FOR PLUMBING / MECHANICAL INSPECTION

DATE: 09.10.2014 TIME: _____ : _____ AM / PM
 JOB ADDRESS: 4720 Oak Lane
 PERMIT NUMBER: PA 12742

- Pass Fail Street Clean In Front of Property- (Nothing in Gutter)
 - Pass Fail Dirt, Mud, Construction Tracks in Front of Property
 - Pass Fail Trash Anywhere on Property
 - Pass Fail O-Tolerance for Lunch Trash This May Result in Project to be Temporarily Shut Down!
 - Pass Fail Dumpster full to the Lip & Needs to be Serviced
 - Pass Fail Port-O-Can Door Facing Away From Street
 - Pass Fail Port-O-Can Screened and/or Needs Maintenance
 - Pass Fail Tree Protective Fencing Down
 - Pass Fail Filter Fabric Fencing Down
 - Pass Fail High Grass and/or Tall Weeds
 - Pass Fail Overall Condition of Construction Site Good _____ Poor
- _____ Verbal Warning _____ Site Cleaned at Insp. _____ City Citation Issued _____ City Notified

INSPECTOR : Joe Moore w/ HDR Engineering. Thursday
Chuck Esklund INSPECTION DATE: 09.11.14

PLUMBING	MECHANICAL
1. Water line <input type="checkbox"/>	1. Vent Hood <input type="checkbox"/>
2. Rough In <input type="checkbox"/>	2. Rough/cover <input type="checkbox"/>
3. Top Out <input type="checkbox"/>	3. Mech Final <input type="checkbox"/>
4. Shower Pan <input type="checkbox"/>	4. Water Heater Final <input type="checkbox"/>
5. Sewer Line <input type="checkbox"/>	5. Fire Sprinkler cover <input type="checkbox"/> <small>(need MVFD approval)</small>
6. WC Flange <input type="checkbox"/>	6. Fire Sprinkler Final <input type="checkbox"/>
7. GTO <input type="checkbox"/>	
8. Plumbing Final <input type="checkbox"/>	
9. Pool Drainage <input type="checkbox"/>	
10. <u>Site Drainage</u> <input checked="" type="checkbox"/>	
11. Irrigation Final <input type="checkbox"/>	
12. Other <input type="checkbox"/>	

PASS	FAIL
DATE: <u>9-11-14</u>	
TIME: <u>11:35</u>	
INSPECTOR: <u>Joe Moore</u>	

CONTRACTOR/CALLER NAME: Benjamin Ramos
 CONTACT TEL/PGR/MOBILE: The Artisan Group
(832) 807-4613

INSPECTOR COMMENTS: roof drains
roof drains running from rough
through inside walls and stabbing
out through outside wall inspected.

REQUEST FOR PLUMBING / MECHANICAL INSPECTION

DATE: 09.10.14 TIME: _____ : _____ AM / PM

JOB ADDRESS: 11326 Piney Point Rd

PERMIT NUMBER: PA 13042

- Pass Fail Street Clean In Front of Property- (Nothing in Gutter)
 - Pass Fail Dirt, Mud, Construction Tracks in Front of Property
 - Pass Fail Trash Anywhere on Property
 - Pass Fail O-Tolerance for Lunch Trash This May Result in Project to be Temporarily Shut Down!
 - Pass Fail Dumpster full to the Lip & Needs to be Serviced
 - Pass Fail Port-O-Can Door Facing Away From Street
 - Pass Fail Port-O-Can Screened and/or Needs Maintenance
 - Pass Fail Tree Protective Fencing Down
 - Pass Fail Filter Fabric Fencing Down
 - Pass Fail High Grass and/or Tall Weeds
 - Pass Fail Overall Condition of Construction Site _____ Good _____ Poor
- ___ Verbal Warning ___ Site Cleaned at Insp. ___ City Citation Issued ___ City Notified

Thursday

INSPECTOR: Joe Moore w/ HBR Engineering INSPECTION DATE: 09.11.14

PLUMBING		MECHANICAL	
1. Water line	<input type="checkbox"/>	1. Vent Hood	<input type="checkbox"/>
2. Rough In	<input type="checkbox"/>	2. Rough/cover	<input type="checkbox"/>
3. Top Out	<input type="checkbox"/>	3. Mech Final	<input type="checkbox"/>
4. Shower Pan	<input type="checkbox"/>	4. Water Heater Final	<input type="checkbox"/>
5. Sewer Line	<input type="checkbox"/>	5. Fire Sprinkler cover <small>(need MVFD approval)</small>	<input type="checkbox"/>
6. WC Flange	<input type="checkbox"/>	6. Fire Sprinkler Final	<input type="checkbox"/>
7. GTO	<input type="checkbox"/>		
8. Plumbing Final	<input type="checkbox"/>		
9. Pool Drainage	<input type="checkbox"/>		
10. Site Drainage	<input checked="" type="checkbox"/>		
11. Irrigation Final	<input type="checkbox"/>		
12. Other	<input type="checkbox"/>		

PASS	FAIL
DATE: <u>9-11-14</u>	
TIME: <u>11:00</u>	
INSPECTOR: <u>Joe Moore</u>	

CONTRACTOR/CALLER NAME: Stephen Oglesby

CONTACT TEL/PGR/MOBILE: Oglesby Interest LLC

INSPECTOR COMMENTS: (832) 687-8396 -
site drainage - re-inspection.

REQUEST FOR **PLUMBING** / MECHANICAL INSPECTION

DATE: 09.10.2014 TIME: _____ : _____ AM / PM Road
 JOB ADDRESS: 5000 S. Piney Point
 PERMIT NUMBER: PH 13640

- Pass Fail Street Clean In Front of Property- (Nothing in Gutter)
- Pass Fail Dirt, Mud, Construction Tracks in Front of Property
- Pass Fail Trash Anywhere on Property
- Pass Fail O-Tolerance for Lunch Trash This May Result in Project to be Temporarily Shut Down!
- Pass Fail Dumpster full to the Lip & Needs to be Serviced
- Pass Fail Port-O-Can Door Facing Away From Street
- Pass Fail Port-O-Can Screened and/or Needs Maintenance
- Pass Fail Tree Protective Fencing Down
- Pass Fail Filter Fabric Fencing Down
- Pass Fail High Grass and/or Tall Weeds
- Pass Fail Overall Condition of Construction Site Good _____ Poor
- _____ Verbal Warning _____ Site Cleaned at Insp. _____ City Citation Issued _____ City Notified

INSPECTOR: Chuck Erlund Thursday
 INSPECTION DATE: 09.11.14

PLUMBING	MECHANICAL
1. Water line <input type="checkbox"/>	1. Vent Hood <input type="checkbox"/>
2. Rough In <input type="checkbox"/>	2. Rough/cover <input type="checkbox"/>
3. Top Out <input type="checkbox"/>	3. Mech Final <input type="checkbox"/>
4. Shower Pan <input type="checkbox"/>	4. Water Heater Final <input type="checkbox"/>
5. Sewer Line <input type="checkbox"/>	5. Fire Sprinkler cover <input type="checkbox"/> <small>(need MVFD approval)</small>
6. WC Flange <input type="checkbox"/>	6. Fire Sprinkler Final <input type="checkbox"/>
7. GTO <input type="checkbox"/>	
8. Plumbing Final <input type="checkbox"/>	
9. Pool Drainage <input type="checkbox"/>	
10. Site Drainage <input type="checkbox"/>	
11. Irrigation Final <input type="checkbox"/>	
12. Other <input type="checkbox"/>	

PASS	FAIL
DATE: <u>9-11-14</u>	
TIME: <u>08:45</u>	
INSPECTOR: <u>CE</u>	

CONTRACTOR/CALLER NAME: Ed A Plumbing
 CONTACT TEL/PGR/MOBILE: (281) 227-1331
 INSPECTOR COMMENTS: sewer disconnect re-inspection

OK