## REQUEST FOR INSPECTION

CALL DATE: 9129/2027 PROPERTY ADDRESS: 3 Face		E CAM PM  PERMIT NUMBER: 1914			
INSPECTION INFORMATION  INSPECTOR:  Bob Baldwin  Jason Bienek  Cary Moran  City Engineer  A m Colog					
Demolition	Generator Concrete Steel Pa	d Mechanical Cover			
Temporary Tree Protection	Generator Final - Operative	Mechanical Vent Hood			

11 16					
	Demolition	Generator Concrete Steel Pad	Mechanical Cover		
	Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood		
	Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal		
	Piers /	Fence Final	Mechanical Box Seal		
	Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up		
	Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final		
	Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out		
	Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)		
Ī	Ridge Height - Verification	Electrical T-Pole	Mechanical Final (Wing Room)		
	Stair Compliance	Electrical Cover	Sewer Disconnect		
	Framing Only	Electrical Ditch Cover	Plumbing Water Line		
	Frame Cover	Electrical TCI	Plumbing Sewer Line		
	Poly Seal	Electrical Reconnect	Plumbing Ground		
	Insulation	Pool Electrical Underground	Plumbing Shower Pan/Wall Board		
	Wall Board Interior	Pool Electrical Cover	Plumbing Gas (GT0- House)		
-	Brick Tie	Pool Electrical Final	Plumbing Cover		
1	Stucco Lathe	Electrical Final	Plumbing Final_		
	Building Final	Temporary Drainage	Pool Plumbing Cover		
	Irrigation Trench / Tree Final	Drainage Partial /	Pool Plumbing Vacuum Breaker, P-Trap		
	Driveway / Steel	Drainage Cover	Plumbing Pool Final		
	Driveway Final	Drainage Final	Water Heater Final		
	Sidewalk/Flatwork/Pavers Steel	Fire Sprinkler Cover	Irrigation Final		
	Sidewalk/Flatwork/Paver Final	Fire Sprinkler Final	Other/Miscellaneous		
	CONTRACTOR NAME: 800 Builders (Clayton) PASS FAI				
	CONTACT PHONE/EMAIL:# 979-224-6593 DATE: 9/29/22				
	INSPECTOR COMMENTS: Diainage Cover		TIME: //=/5		
	OK to cover all	drainage pipes	INSPECTOR: Cole Malie		
-	F/L elevations for	inlets along Nort	th side of property		
	and inlet in S	Wiorner appear	higher than		
	Shown on the dra	ainage plan Verity	FIL elevations		
	or revise droinage plan and submit.				
	- Appears curb cut and repair was not soweut and				
	dowelled in place as shown on the drainage plun lurb				
	repair also appears rocked Re-construct per detail.				
	Existing outlets through rurb not shown on drainage				
-1	- Filter Fabric Fencing required on East Re-Inspection Fee Required				
5,	Side of lot.				