REQUEST FOR INSPECTION

CALL DATE: 1-23-23 TIME 10: 30 AM PM					
PROPERTY ADDRESS: 11110 5 Country 59 PERMIT NUMBER: 19138 INSPECTOR Bob Baldwi					
			Demolition	Generator Concrete Steel Pad	Mechanical Cover
			Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal			
Piers	Fence Final	Mechanical Box Seal			
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up			
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final			
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out			
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)			
Ridge Height - Verification	Synthetic Turf	Mechanical Final (Wine Room)			
Stair Compliance	Electrical T-Pole	Sewer Disconnect			
Framing Only	Electrical Cover	Plumbing Water Line			
Frame Cover	Electrical Ditch Cover	Plumbing Sewer Line			
Poly Seal	Electrical TCI	Plumbing Ground			
Insulation	Electrical Reconnect	Plumbing Shower Pan/Wall Board			
Wall Board Interior	Pool Electrical Underground	Plumb Gas: House / Pool / Generator			
Brick Tie	Pool Electrical Cover	Plumbing Cover			
Stucco Lathe	Pool Electrical Final	Plumbing Final			
Building Final	Flectrical Final	Pool Plumbing Cover			
Tree Final	Temporary Drainage	Pool Plumbing Vacuum Breaker, P-Trap			
Driveway / Steel	Drainage Partial	Plumbing Pool Final			
Driveway Final	Drainage Cover	Water Heater Final			
Sidewalk/Flatwork/Pavers Steel	Drainage Final	Irrigation Trench / Final			
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Cover / Final	Other/Miscellaneous			
CONTRACTOR NAME: 15 Electricis		PASS FAIL			
CONTACT PHONE/EMAIL: Bondy		DATE: 1-23-23			
INSPECTOR COMMENTS: 213-292-8475		TIME: 10:30			
		INSPECTOR: Spison			
Fixture needs	to be planted	Re-Inspection Fee Required			
off,					
OFI in bathdoesn't tep					