REQUEST FOR INSPECTION CALL DATE: 10-6-23 TIME : CAM/PM PROPERTY ADDRESS: 11010 5 CORNTAN 59 PERMIT NUMBER: 1940 8

PROPERTY ADDRESS	PERIOTI NOWIBER:	į.	
	INSPECTOR		
☑ Bob Baldwin ☐ Jas	son Bienek 🛘 Cary Moran 🗖 Jose Gomez 🗘 City Engineer	The same of the sa	

- A	•				
Demolition	Generator Concrete Steel Pad	Mechanical Cover			
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood			
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal			
Piers	Fence Final	Mechanical Box Seal			
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up			
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final			
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out			
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)			
Ridge Height - Verification	Synthetic Turf	Mechanical Final (Wine Room)			
Stair Compliance	Electrical T-Pole	Sewer Disconnect			
Framing Only	Electrical Cover	Plumbing Water Line			
Frame Cover	Electrical Ditch Cover	Plumbing Sewer Line			
Poly Seal	Electrical TCI	Plumbing Ground			
Insulation	Electrical Reconnect	Plumbing Shower Pan/Wall Board			
Wall Board Interior	Pool Electrical Underground	Plumb Gas: House / Pool / Generator			
Brick Tie	Pool Electrical Cover	Plumbing Cover			
Stucco Lathe	Pool Electrical Final	Plumbing Final			
Building Final	Electrical Final	Pool Plumbing Cover			
Tree Final	Temporary Drainage	Pool Plumbing Vacuum Breaker, P-Trap			
Driveway / Steel	Drainage Partial	Plumbing Pool Final			
Driveway Final	Drainage Cover	Water Heater Final			
Sidewalk/Flatwork/Pavers Steel	Drainage Final	Irrigation Trench / Final			
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Cover / Final	Other/Miscellaneous			
CONTRACTOR NAME: Tower	PASS FAIL				
CONTACT PHONE/EMAIL:	DATE: 10-6-23				
INSPECTOR COMMENTS: Part	TIME: 12:40				
only	INSPECTOR: RAK 373				
Re-Inspection Fee Require					
Misst have Dermit Dosted for					
all inspections					
September 2011 And September 2011					