REQUEST FOR INSPECTION CALL DATE: 2-23-24 TIME : AM PM PROPERTY ADDRESS: 11505 Memoria Dv. PERMIT NUMBER: 19758 INSPECTOR

Demolition	Generator Concrete Steel P	Pad Mechanical Cover
Temporary Tree Protection Fencing	Generator Final - Operativ	ve Mechanical Vent Hood
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal
Piers	Fence Final	Mechanical Box Seal
Foundation Repair	Pool Stake Out & Pool Doc Box S	Set Up Mechanical Air Make Up
Foundation Steel – Survey Ver	rified Deck Steel / Pool Steel	Mechanical Final
Hurricane Strapping – Exterior	r Wall Deck Final / Pool Final	Mechanical Change Out
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)
Ridge Height - Verification	n Synthetic Turf	Mechanical Final (Wine Room)
Stair Compliance	Electrical T-Pole	Sewer Disconnect
Framing Only	Electrical Cover	Plumbing Water Line
Frame Cover	Electrical Ditch Cover	Plumbing Sewer Line
Poly Seal	Electrical TCI	Plumbing Ground
Insulation	Electrical Reconnect	Plumbing Shower Pan/Wall Board
Wall Board Interior	Pool Electrical Undergroun	Plumb Gas: House / Pool / Generator
Brick Tie	Pool Electrical Cover	Plumbing Cover
Stucco Lathe	Pool Electrical Final	Plumbing Final
Building Final	Electrical Final	Pool Plumbing Cover
Tree Final	Temporary Drainage	Pool Plumbing Vacuum Breaker, P-Trap
Driveway / Steel	Drainage Partial	Plumbing Pool Final
Driveway Final	Drainage Cover	Water Heater Final
Sidewalk/Flatwork/Pavers St	teel Drainage Final	Irrigation Trench / Final
Sidewalk/Flatwork/Paver Fir	nal Fire Sprinkler Cover / Final	l Other/Miscellaneous
CONTRACTOR NAME: Meistad Hanbing		PASS FAIL
CONTACT PHONE/EMAIL: Branda 7-466-5159		DATE: 2-23-24
INSPECTOR COMMENTS:		TIME: //:/5
ALCES	INSPECTOR: 10 B 3300	
Re-Inspection Fee Require		