BEQUEST FOR DI MARRIAGO ANTONIO	
REQUEST FOR PLUMBING / MECHANICAL INSPECTION	
DATE: /- 28-21 TIME : AM /PM	
JOB ADDRESS: 112/9 Hermosa Court	
PERMIT NUMBER: 17157	
☐ Pass ☐ Fail Street Clean In Front of Property- (Nothing in Gutter)	
☐ Pass ☐ Fail Dirt, Mud, Construction Tracks in Front of Property ☐ Pass ☐ Fail Trash Anywhere on Property ☐ Pass ☐ Fail Trash Anywhere on Property	
Lass Land O-Tolerance for Lunch Trash This May Beauting	
□ Pass □ Fail Dumpster full to the Lip & Needs to be Serviced □ Pass □ Fail Port-O-Can Door Facing Away From Street	
- · · · · · · · · · · · · · · · · · · ·	
☐ Pass ☐ Fail Tree Protective Fencing Down ☐ Pass ☐ Fail Filter Fabric Fencing Down	
□ Fass □ Fall High Grass and/or Tall Woods	
□ Pass □ Fail Overall Condition of Construction Site Good Poor Verbal Warning Site Cleaned at Insp City Citation Issued City Notified	
Site Cleaned at InspCit	y Citation IssuedCity Notified
INSPECTOR: Bob Baldwin	INSPECTION DATE: 1-28-21
PLUMBING	
1. Water line	MECHANICAL
2. Rough In 3. Top Out	1. Vent Hood 2. Rough/cover
4. Shower Pan	3. Mech Final
5. Sewer Line 6. WC Flange	4. Water Heater Final
7. GTO	5. Fire Sprinkler cover (need MVFD approval)
8. Plumbing Final 9. Pool Drainage	6. Fire Sprinkler Final
10 Site Drainage	
11. Irrigation Final	PASS FAIL DATE: /-28-2/
	TIME: 12:30
CONTRACTORIOALI	INSPECTOR: RLB 3330
CONTRACTOR/CALLER NAME: Tower Plumbing	
ONTACT TEL/PGR/MOBILE: 713-726-066	/
NSPECTOR COMMENTS:	
M 51	rower Pans
	140
	8
	Reinspection fee required