

REQUEST FOR ELECTRICAL INSPECTION

DATE: 2-25-21 TIME: 2:15 AM / PM

JOB ADDRESS: 8502 San Felipe

PERMIT NUMBER: 17570

INSPECTION DATE:

Codes Used: NFPA 70 - NEC 2017

ELECTRICAL INSPECTORS: 1) Jason Bienek 2) Bob Baldwin

1. Temp Sump Pump Connection ☐
2. T-pole ☐
3. Ditch Cover ☐
4. Slab Cover ☐
5. Wall / Celing Cover ☐
6. TCI ☐
7. Meter Loop And Service ☐
8. Reconnect ☐
9. Electrical Final ☐
10. Landscape Lighting Cover ☐
11. Landscape Lighting Final ☐

- | | |
|-------------------------------|--------------------------|
| 1. Electrical Pool Cover | ☐ |
| 2. Electrical Pool Final | ☐ |
| 1. Generator Ditch Cover | ☐ |
| 2. Generator Electrical Final | ☐ |
| 1. Partial / See Comments | ☐ |

upstairs

PASS

FAIL

DATE: 2-25-21

TIME: 12:15

INSPECTOR: *ZB*

CONTRACTOR/CALLER NAME: New Heights Electric

CONTACT TEL/PGR/MOBILE: Hector 346-303-1860

INSPECTOR COMMENTS: _____

☐ Reinspection fee required

REQUEST FOR ELECTRICAL INSPECTION

DATE: 2-22-21 TIME 12:05: AM / PM

JOB ADDRESS: 8502 San Felipe

PERMIT NUMBER: 17533

INSPECTION DATE:

Codes Used: **NFPA 70 - NEC 2017**

ELECTRICAL INSPECTORS: 1) Jason Bienek 2) Bob Baldwin

- 1. Temp Sump Pump Connection ☐
- 2. T-pole ☐
- 3. Ditch Cover ☐
- 4. Slab Cover ☐
- 5. Wall / Ceiling Cover ☐
- 6. TCI ☐
- 7. Meter Loop And Service ☐
- 8. Reconnect ☐
- 9. Electrical Final ☐
- 10. Landscape Lighting Cover ☐
- 11. Landscape Lighting Final ☐

- 1. Electrical Pool Cover ☐
- 2. Electrical Pool Final ☐
- 1. Generator Ditch Cover ☐
- 2. Generator Electrical Final ☐
- 1. Partial / See Comments ☐

Kitchen

PASS	FAIL
DATE: <u>2-22-21</u>	
TIME: <u>12:05</u>	
INSPECTOR: <u>JB</u>	

CONTRACTOR/CALLER NAME: Morgan Complete

CONTACT TEL/PGR/MOBILE: Buben-346-394-0661

INSPECTOR COMMENTS:

☐ Reinspection fee required

REQUEST FOR ELECTRICAL INSPECTION

DATE: 2-9-21 TIME: _____ : AM / PM

JOB ADDRESS: 8502 San Felipe

PERMIT NUMBER: 15750

INSPECTION DATE:

Codes Used: **NFPA 70 - NEC 2017**

ELECTRICAL INSPECTORS: 1) Jason Bienek 2) Bob Baldwin

- 1. Temp Sump Pump Connection ☐
- 2. T-pole ☐
- 3. Ditch Cover ☐
- 4. Slab Cover ☐
- 5. Wall / Ceiling Cover ☐
- 6. TCI ☐
- 7. Meter Loop And Service ☐
- 8. Reconnect ☐
- 9. Electrical Final ☐
- 10. Landscape Lighting Cover ☐
- 11. Landscape Lighting Final ☐

- 1. Electrical Pool Cover ☐
- 2. Electrical Pool Final ☐
- 1. Generator Ditch Cover ☐
- 2. Generator Electrical Final ☐
- 1. Partial / See Comments ☐

PASS

FAIL

DATE: 2-9-21

TIME: 12:00

INSPECTOR: JB

CONTRACTOR/CALLER NAME: New Heights Electric

CONTACT TEL/PGR/MOBILE: Hector 346-303-1860

INSPECTOR COMMENTS: _____

Missing blank plate closet
switches to close to shower
missing plates upstairs

☒ Reinspection fee required

REQUEST FOR ELECTRICAL INSPECTION

DATE: 2-9-21 TIME: : AM / PM

JOB ADDRESS: 8502 San Felipe

PERMIT NUMBER: 17533

INSPECTION DATE:

Codes Used: **NFPA 70 - NEC 2017**

ELECTRICAL INSPECTORS: 1) Jason Bienek 2) Bob Baldwin

- 1. Temp Sump Pump Connection ☐
- 2. T-pole ☐
- 3. Ditch Cover ☐
- 4. Slab Cover ☐
- 5. Wall / Ceiling Cover ☐
- 6. TCI ☐
- 7. Meter Loop And Service ☐
- 8. ~~Reconnect~~ ☐
- 9. Electrical Final ☐
- 10. Landscape Lighting Cover ☐
- 11. Landscape Lighting Final ☐

Kitchen

- 1. Electrical Pool Cover ☐
- 2. Electrical Pool Final ☐
- 1. Generator Ditch Cover ☐
- 2. Generator Electrical Final ☐
- 1. Partial / See Comments ☐

PASS

FAIL

DATE: 2-9-21

TIME: 12:00

INSPECTOR: JB

CONTRACTOR/CALLER NAME: Morgan Complete

CONTACT TEL/PGR/MOBILE: Marin 346-394-0661

INSPECTOR COMMENTS:

Disposables not booked up
Breakfast Room fixture not hung or booked
off

☒ Reinspection fee required