

REQUEST FOR STRUCTURAL INSPECTION

CALL DATE: 2-26-21 TIME 11:30 AM/PM

PROPERTY ADDRESS: 11306 Claymore

PERMIT NUMBER: 17070

- ☐ Pass ☐ Fail Street Clean In Front of Property- (Nothing in Gutter)
☐ Pass ☐ Fail Dirt, Mud, Construction Tracks in Front of Property
☐ Pass ☐ Fail Trash Anywhere on Property
☐ Pass ☐ Fail O-Tolerance for Lunch Trash This May Result in Project to be Temporarily Shut Down!
☐ Pass ☐ Fail Dumpster full to the Lip & Needs to be Serviced
☐ Pass ☐ Fail Port-O-Can Door Facing Away From Street
☐ Pass ☐ Fail Port-O-Can Screened and/or Needs Maintenance
☐ Pass ☐ Fail Tree Protective Fencing Down
☐ Pass ☐ Fail Filter Fabric Fencing Down
☐ Pass ☐ Fail High Grass and/or Tall Weeds
☐ Pass ☐ Fail Overall Condition of Construction Site Good Poor
Verbal Warning Site Cleaned at Insp. City Citation Issued City Notified

DATE: 2-26-21 TIME 11:30 AM/PM

INSPECTOR: 1) Jason Bienek 2) Bob Baldwin

INSPECTION TYPE

- | | | | |
|----------------------------|--------------------------|-------------------------------|-------------------------------------|
| 1. PRE CONSTRUCTION SITE | <input type="checkbox"/> | 1. POOL STAKE OUT/POOL SET-UP | <input type="checkbox"/> |
| 2. PIERS | <input type="checkbox"/> | 2. POOL STEEL | <input type="checkbox"/> |
| 3. FOUNDATION STEEL | <input type="checkbox"/> | 3. POOL DECK/PATIO STEEL | <input type="checkbox"/> |
| 4. RIDGE HEIGHT | <input type="checkbox"/> | 4. POOL FENCING | <input type="checkbox"/> |
| 5. HURRICANE TIES | <input type="checkbox"/> | 4. POOL FINAL | <input checked="" type="checkbox"/> |
| 6. STUCCO LATHE/BRICK TIES | <input type="checkbox"/> | 1. FENCE POST HOLE | <input type="checkbox"/> |
| 7. FRAMING / FRAMING COVER | <input type="checkbox"/> | 2. FENCE FINAL | <input type="checkbox"/> |
| 8. BUILDING FINAL | <input type="checkbox"/> | 1. DRIVEWAY/FLATWORK FORMS | <input type="checkbox"/> |
| 9. TREE FINAL | <input type="checkbox"/> | 2. DRIVEWAY FINAL | <input type="checkbox"/> |
| 10. ROOF Final/ DEMO FINAL | <input type="checkbox"/> | 3. OTHER | <input type="checkbox"/> |
| 11. Generator Steel | <input type="checkbox"/> | 4. TRENCH | <input type="checkbox"/> |
| 12. Generator Final | <input type="checkbox"/> | 5. TEMP FENCING | <input type="checkbox"/> |

CONTRACTOR/CALLER NAME: Alanza LLC

CONTACT TEL/PGR/MOBILE: JOSE

INSPECTOR COMMENTS: 713-724-9500

Missing Pool Barrier Westside
Door Alarms not operational
Gate on East Side doesn't meet Pool Barrier Requirement
Fence around Pool Equipment - Need 3' of Clearance
in Front of Panel

PASS	<input checked="" type="checkbox"/> FAIL
DATE:	<u>2-26-21</u>
TIME:	<u>11:30</u>
INSPECTOR:	<u>TB</u>

☒ Reinspection fee required